

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE:

9/26/16

CHECK COMPLETED BY:

[Handwritten signature]

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y / N
27	Building 31 roof look south of to roof of Building 27	P092	Y / N
10A	Building 31 roof look north to roof of Building 10	P131	Y / N
10C	Building 31 roof look north to roof of Building 10	P005	Y / N
31	Building 31 roof	P010	Y / N
31	Building 31 roof	P010	Y / N
31	Building 31 roof	P010	Y / N
31	Building 31 roof	P010-1	Y / N
31	Building 31 roof	P024	Y / N
31	Building 31 roof	P026	Y / N
31	Building 31 roof	P026	Y / N
31	Building 31 roof	P028/P110	Y / N
10A	Building 31 roof look north to roof of Building 10	P031	Y / N
10A	Building 31 roof look north to roof of Building 10	P031	Y / N
10A	Building 31 roof look north to roof of Building 10	P031	Y / N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y / N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y / N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y / N
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y / N
10	Building 31 roof look north to roof of Building 10	P069	Y / N
16	Building 31 roof look north to roof of Building 16	P080	Y / N
16	Building 31 roof look north to roof of Building 16	P080	Y / N
16	Building 31 roof look north to roof of Building 16	P080	Y / N
10	Building 31 roof look north to roof of Building 10	P094	Y / N
27	Building 31 roof look south of to roof of Building 27	P096	Y / N
27	Building 31 roof look south of to roof of Building 27	P096	Y / N
25	North side of Building 25	P098	Y / N
25	North side of Building 25	P098	Y / N
9	West side of Building 9	P099	Y / N
9	Building 31 roof look west to east side wall of Building 9	P099	Y / N
10C	Building 31 roof look north to roof of Building 10	P100	Y / N
10C	Building 31 roof look north to roof of Building 10	P101	Y / N
31	Building 31 roof	P102	Y / N
13	Building 31 roof look north west to roof of Building 13	P127	Y / N
13	Building 31 roof look north west to roof of Building 13	P127	Y / N
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y / N
90	Building 31 look west to east wall of LIB Plant	P129	Y / N
90	Building 31 look west to east wall of LIB Plant	P129	Y / N
90	Building 31 look west to lower roof of LIB Plant	P129	Y / N
90	Building 31 look west to upper roof of LIB Plant	P129	Y / N
90	Building 31 look west to upper roof of LIB Plant	P129	Y / N
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y / N

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 9/19/16CHECK COMPLETED BY: 

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y / (N)
27	Building 31 roof look south of to roof of Building 27	P092	Y (N)
10A	Building 31 roof look north to roof of Building 10	P131	Y (N)
10C	Building 31 roof look north to roof of Building 10	P005	Y (N)
31	Building 31 roof	P010	Y (N)
31	Building 31 roof	P010	Y (N)
31	Building 31 roof	P010	Y (N)
31	Building 31 roof	P010-1	Y (N)
31	Building 31 roof	P024	Y (N)
31	Building 31 roof	P026	Y (N)
31	Building 31 roof	P026	Y (N)
31	Building 31 roof	P028/P110	Y (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y (N)
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y (N)
10	Building 31 roof look north to roof of Building 10	P069	Y (N)
16	Building 31 roof look north to roof of Building 16	P080	Y (N)
16	Building 31 roof look north to roof of Building 16	P080	Y (N)
16	Building 31 roof look north to roof of Building 16	P080	Y (N)
10	Building 31 roof look north to roof of Building 10	P094	Y (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y (N)
25	North side of Building 25	P098	Y (N)
25	North side of Building 25	P098	Y (N)
9	West side of Building 9	P099	Y (N)
9	Building 31 roof look west to east side wall of Building 9	P099	Y (N)
10C	Building 31 roof look north to roof of Building 10	P100	Y (N)
10C	Building 31 roof look north to roof of Building 10	P101	Y (N)
31	Building 31 roof	P102	Y (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y (N)
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y (N)
90	Building 31 look west to lower roof of LIB Plant	P129	Y (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y (N)
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y (N)

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 9/12/16CHECK COMPLETED BY: 

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y / (N)
27	Building 31 roof look south of to roof of Building 27	P092	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P131	Y / (N)
10C	Building 31 roof look north to roof of Building 10	P005	Y / (N)
31	Building 31 roof	P010	Y / (N)
31	Building 31 roof	P010	Y / (N)
31	Building 31 roof	P010	Y / (N)
31	Building 31 roof	P010-1	Y / (N)
31	Building 31 roof	P024	Y / (N)
31	Building 31 roof	P026	Y / (N)
31	Building 31 roof	P026	Y / (N)
31	Building 31 roof	P028/P110	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y / (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y / (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y / (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y / (N)
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y / (N)
10	Building 31 roof look north to roof of Building 10	P069	Y / (N)
16	Building 31 roof look north to roof of Building 16	P080	Y / (N)
16	Building 31 roof look north to roof of Building 16	P080	Y / (N)
16	Building 31 roof look north to roof of Building 16	P080	Y / (N)
10	Building 31 roof look north to roof of Building 10	P094	Y / (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y / (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y / (N)
25	North side of Building 25	P098	Y / (N)
25	North side of Building 25	P098	Y / (N)
9	West side of Building 9	P099	Y / (N)
9	Building 31 roof look west to east side wall of Building 9	P099	Y / (N)
10C	Building 31 roof look north to roof of Building 10	P100	Y / (N)
10C	Building 31 roof look north to roof of Building 10	P101	Y / (N)
31	Building 31 roof	P102	Y / (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y / (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y / (N)
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y / (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y / (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y / (N)
90	Building 31 look west to lower roof of LIB Plant	P129	Y / (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y / (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y / (N)
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y / (N)

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 9/6/16CHECK COMPLETED BY: T. [Signature]

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y/N
27	Building 31 roof look south of to roof of Building 27	P092	Y/N
10A	Building 31 roof look north to roof of Building 10	P131	Y/N
10C	Building 31 roof look north to roof of Building 10	P005	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010-1	Y/N
31	Building 31 roof	P024	Y/N
31	Building 31 roof	P026	Y/N
31	Building 31 roof	P026	Y/N
31	Building 31 roof	P028/P110	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y/N
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y/N
10	Building 31 roof look north to roof of Building 10	P069	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
10	Building 31 roof look north to roof of Building 10	P094	Y/N
27	Building 31 roof look south of to roof of Building 27	P096	Y/N
27	Building 31 roof look south of to roof of Building 27	P096	Y/N
25	North side of Building 25	P098	Y/N
25	North side of Building 25	P098	Y/N
9	West side of Building 9	P099	Y/N
9	Building 31 roof look west to east side wall of Building 9	P099	Y/N
10C	Building 31 roof look north to roof of Building 10	P100	Y/N
10C	Building 31 roof look north to roof of Building 10	P101	Y/N
31	Building 31 roof	P102	Y/N
13	Building 31 roof look north west to roof of Building 13	P127	Y/N
13	Building 31 roof look north west to roof of Building 13	P127	Y/N
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y/N
90	Building 31 look west to east wall of LIB Plant	P129	Y/N
90	Building 31 look west to east wall of LIB Plant	P129	Y/N
90	Building 31 look west to lower roof of LIB Plant	P129	Y/N
90	Building 31 look west to upper roof of LIB Plant	P129	Y/N
90	Building 31 look west to upper roof of LIB Plant	P129	Y/N
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y/N

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE:

8/29/16

CHECK COMPLETED BY:

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y (N)
27	Building 31 roof look south of to roof of Building 27	P092	Y (N)
10A	Building 31 roof look north to roof of Building 10	P131	Y (N)
10C	Building 31 roof look north to roof of Building 10	P005	Y (N)
31	Building 31 roof	P010	Y (N)
31	Building 31 roof	P010	Y (N)
31	Building 31 roof	P010	Y (N)
31	Building 31 roof	P010-1	Y (N)
31	Building 31 roof	P024	Y (N)
31	Building 31 roof	P026	Y (N)
31	Building 31 roof	P026	Y (N)
31	Building 31 roof	P028/P110	Y (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y (N)
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y (N)
10	Building 31 roof look north to roof of Building 10	P069	Y (N)
16	Building 31 roof look north to roof of Building 16	P080	Y (N)
16	Building 31 roof look north to roof of Building 16	P080	Y (N)
16	Building 31 roof look north to roof of Building 16	P080	Y (N)
10	Building 31 roof look north to roof of Building 10	P094	Y (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y (N)
25	North side of Building 25	P098	Y (N)
25	North side of Building 25	P098	Y (N)
9	West side of Building 9	P099	Y (N)
9	Building 31 roof look west to east side wall of Building 9	P099	Y (N)
10C	Building 31 roof look north to roof of Building 10	P100	Y (N)
10C	Building 31 roof look north to roof of Building 10	P101	Y (N)
31	Building 31 roof	P102	Y (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y (N)
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y (N)
90	Building 31 look west to lower roof of LIB Plant	P129	Y (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y (N)
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y (N)

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 8/22/16

CHECK COMPLETED BY: [Signature]

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y/N
27	Building 31 roof look south of to roof of Building 27	P092	Y/N
10A	Building 31 roof look north to roof of Building 10	P131	Y/N
10C	Building 31 roof look north to roof of Building 10	P005	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010-1	Y/N
31	Building 31 roof	P024	Y/N
31	Building 31 roof	P026	Y/N
31	Building 31 roof	P026	Y/N
31	Building 31 roof	P028/P110	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y/N
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y/N
10	Building 31 roof look north to roof of Building 10	P069	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
10	Building 31 roof look north to roof of Building 10	P094	Y/N
27	Building 31 roof look south of to roof of Building 27	P096	Y/N
27	Building 31 roof look south of to roof of Building 27	P096	Y/N
25	North side of Building 25	P098	Y/N
25	North side of Building 25	P098	Y/N
9	West side of Building 9	P099	Y/N
9	Building 31 roof look west to east side wall of Building 9	P099	Y/N
10C	Building 31 roof look north to roof of Building 10	P100	Y/N
10C	Building 31 roof look north to roof of Building 10	P101	Y/N
31	Building 31 roof	P102	Y/N
13	Building 31 roof look north west to roof of Building 13	P127	Y/N
13	Building 31 roof look north west to roof of Building 13	P127	Y/N
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y/N
90	Building 31 look west to east wall of LIB Plant	P129	Y/N
90	Building 31 look west to east wall of LIB Plant	P129	Y/N
90	Building 31 look west to lower roof of LIB Plant	P129	Y/N
90	Building 31 look west to upper roof of LIB Plant	P129	Y/N
90	Building 31 look west to upper roof of LIB Plant	P129	Y/N
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y/N

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 8/15/16CHECK COMPLETED BY: T. [Signature]

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y (N)
27	Building 31 roof look south of to roof of Building 27	P092	Y (N)
10A	Building 31 roof look north to roof of Building 10	P131	Y (N)
10C	Building 31 roof look north to roof of Building 10	P005	Y (N)
31	Building 31 roof	P010	Y (N)
31	Building 31 roof	P010	Y (N)
31	Building 31 roof	P010	Y (N)
31	Building 31 roof	P010-1	Y (N)
31	Building 31 roof	P024	Y (N)
31	Building 31 roof	P026	Y (N)
31	Building 31 roof	P026	Y (N)
31	Building 31 roof	P028/P110	Y (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y (N)
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y (N)
10	Building 31 roof look north to roof of Building 10	P069	Y (N)
16	Building 31 roof look north to roof of Building 16	P080	Y (N)
16	Building 31 roof look north to roof of Building 16	P080	Y (N)
16	Building 31 roof look north to roof of Building 16	P080	Y (N)
10	Building 31 roof look north to roof of Building 10	P094	Y (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y (N)
25	North side of Building 25	P098	Y (N)
25	North side of Building 25	P098	Y (N)
9	West side of Building 9	P099	Y (N)
9	Building 31 roof look west to east side wall of Building 9	P099	Y (N)
10C	Building 31 roof look north to roof of Building 10	P100	Y (N)
10C	Building 31 roof look north to roof of Building 10	P101	Y (N)
31	Building 31 roof	P102	Y (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y (N)
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y (N)
90	Building 31 look west to lower roof of LIB Plant	P129	Y (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y (N)
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y (N)

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 8/8/16

CHECK COMPLETED BY: [Signature]

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y/N
27	Building 31 roof look south of to roof of Building 27	P092	Y/N
10A	Building 31 roof look north to roof of Building 10	P131	Y/N
10C	Building 31 roof look north to roof of Building 10	P005	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010-1	Y/N
31	Building 31 roof	P024	Y/N
31	Building 31 roof	P026	Y/N
31	Building 31 roof	P026	Y/N
31	Building 31 roof	P028/P110	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y/N
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y/N
10	Building 31 roof look north to roof of Building 10	P069	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
10	Building 31 roof look north to roof of Building 10	P094	Y/N
27	Building 31 roof look south of to roof of Building 27	P096	Y/N
27	Building 31 roof look south of to roof of Building 27	P096	Y/N
25	North side of Building 25	P098	Y/N
25	North side of Building 25	P098	Y/N
9	West side of Building 9	P099	Y/N
9	Building 31 roof look west to east side wall of Building 9	P099	Y/N
10C	Building 31 roof look north to roof of Building 10	P100	Y/N
10C	Building 31 roof look north to roof of Building 10	P101	Y/N
31	Building 31 roof	P102	Y/N
13	Building 31 roof look north west to roof of Building 13	P127	Y/N
13	Building 31 roof look north west to roof of Building 13	P127	Y/N
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y/N
90	Building 31 look west to east wall of LIB Plant	P129	Y/N
90	Building 31 look west to east wall of LIB Plant	P129	Y/N
90	Building 31 look west to lower roof of LIB Plant	P129	Y/N
90	Building 31 look west to upper roof of LIB Plant	P129	Y/N
90	Building 31 look west to upper roof of LIB Plant	P129	Y/N
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y/N

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 8/1/16CHECK COMPLETED BY: T. ref

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y (N)
27	Building 31 roof look south of to roof of Building 27	P092	Y (N)
10A	Building 31 roof look north to roof of Building 10	P131	Y (N)
10C	Building 31 roof look north to roof of Building 10	P005	Y (N)
31	Building 31 roof	P010	Y (N)
31	Building 31 roof	P010	Y (N)
31	Building 31 roof	P010	Y (N)
31	Building 31 roof	P010-1	Y (N)
31	Building 31 roof	P024	Y (N)
31	Building 31 roof	P026	Y (N)
31	Building 31 roof	P026	Y (N)
31	Building 31 roof	P028/P110	Y (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y (N)
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y (N)
10	Building 31 roof look north to roof of Building 10	P069	Y (N)
16	Building 31 roof look north to roof of Building 16	P080	Y (N)
16	Building 31 roof look north to roof of Building 16	P080	Y (N)
16	Building 31 roof look north to roof of Building 16	P080	Y (N)
10	Building 31 roof look north to roof of Building 10	P094	Y (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y (N)
25	North side of Building 25	P098	Y (N)
25	North side of Building 25	P098	Y (N)
9	West side of Building 9	P099	Y (N)
9	Building 31 roof look west to east side wall of Building 9	P099	Y (N)
10C	Building 31 roof look north to roof of Building 10	P100	Y (N)
10C	Building 31 roof look north to roof of Building 10	P101	Y (N)
31	Building 31 roof	P102	Y (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y (N)
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y (N)
90	Building 31 look west to lower roof of LIB Plant	P129	Y (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y (N)
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y (N)

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 9/26/16CHECK COMPLETED BY: T. [Signature]

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y / (N)
27	Building 31 roof look south of to roof of Building 27	P092	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P131	Y / (N)
10C	Building 31 roof look north to roof of Building 10	P005	Y / (N)
31	Building 31 roof	P010	Y / (N)
31	Building 31 roof	P010	Y / (N)
31	Building 31 roof	P010	Y / (N)
31	Building 31 roof	P010-1	Y / (N)
31	Building 31 roof	P024	Y / (N)
31	Building 31 roof	P026	Y / (N)
31	Building 31 roof	P026	Y / (N)
31	Building 31 roof	P028/P110	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y / (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y / (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y / (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y / (N)
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y / (N)
10	Building 31 roof look north to roof of Building 10	P069	Y / (N)
16	Building 31 roof look north to roof of Building 16	P080	Y / (N)
16	Building 31 roof look north to roof of Building 16	P080	Y / (N)
16	Building 31 roof look north to roof of Building 16	P080	Y / (N)
10	Building 31 roof look north to roof of Building 10	P094	Y / (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y / (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y / (N)
25	North side of Building 25	P098	Y / (N)
25	North side of Building 25	P098	Y / (N)
9	West side of Building 9	P099	Y / (N)
9	Building 31 roof look west to east side wall of Building 9	P099	Y / (N)
10C	Building 31 roof look north to roof of Building 10	P100	Y / (N)
10C	Building 31 roof look north to roof of Building 10	P101	Y / (N)
31	Building 31 roof	P102	Y / (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y / (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y / (N)
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y / (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y / (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y / (N)
90	Building 31 look west to lower roof of LIB Plant	P129	Y / (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y / (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y / (N)
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y / (N)

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 7/18/16CHECK COMPLETED BY: [Signature]

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y/N
27	Building 31 roof look south of to roof of Building 27	P092	Y/N
10A	Building 31 roof look north to roof of Building 10	P131	Y/N
10C	Building 31 roof look north to roof of Building 10	P005	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010-1	Y/N
31	Building 31 roof	P024	Y/N
31	Building 31 roof	P026	Y/N
31	Building 31 roof	P026	Y/N
31	Building 31 roof	P028/P110	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y/N
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y/N
10	Building 31 roof look north to roof of Building 10	P069	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
10	Building 31 roof look north to roof of Building 10	P094	Y/N
27	Building 31 roof look south of to roof of Building 27	P096	Y/N
27	Building 31 roof look south of to roof of Building 27	P096	Y/N
25	North side of Building 25	P098	Y/N
25	North side of Building 25	P098	Y/N
9	West side of Building 9	P099	Y/N
9	Building 31 roof look west to east side wall of Building 9	P099	Y/N
10C	Building 31 roof look north to roof of Building 10	P100	Y/N
10C	Building 31 roof look north to roof of Building 10	P101	Y/N
31	Building 31 roof	P102	Y/N
13	Building 31 roof look north west to roof of Building 13	P127	Y/N
13	Building 31 roof look north west to roof of Building 13	P127	Y/N
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y/N
90	Building 31 look west to east wall of LIB Plant	P129	Y/N
90	Building 31 look west to east wall of LIB Plant	P129	Y/N
90	Building 31 look west to lower roof of LIB Plant	P129	Y/N
90	Building 31 look west to upper roof of LIB Plant	P129	Y/N
90	Building 31 look west to upper roof of LIB Plant	P129	Y/N
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y/N

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 7/12/16

CHECK COMPLETED BY: T. [Signature]

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y / (N)
27	Building 31 roof look south of to roof of Building 27	P092	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P131	Y / (N)
10C	Building 31 roof look north to roof of Building 10	P005	Y / (N)
31	Building 31 roof	P010	Y / (N)
31	Building 31 roof	P010	Y / (N)
31	Building 31 roof	P010	Y / (N)
31	Building 31 roof	P010-1	Y / (N)
31	Building 31 roof	P024	Y / (N)
31	Building 31 roof	P026	Y / (N)
31	Building 31 roof	P026	Y / (N)
31	Building 31 roof	P028/P110	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y / (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y / (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y / (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y / (N)
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y / (N)
10	Building 31 roof look north to roof of Building 10	P069	Y / (N)
16	Building 31 roof look north to roof of Building 16	P080	Y / (N)
16	Building 31 roof look north to roof of Building 16	P080	Y / (N)
16	Building 31 roof look north to roof of Building 16	P080	Y / (N)
10	Building 31 roof look north to roof of Building 10	P094	Y / (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y / (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y / (N)
25	North side of Building 25	P098	Y / (N)
25	North side of Building 25	P098	Y / (N)
9	West side of Building 9	P099	Y / (N)
9	Building 31 roof look west to east side wall of Building 9	P099	Y / (N)
10C	Building 31 roof look north to roof of Building 10	P100	Y / (N)
10C	Building 31 roof look north to roof of Building 10	P101	Y / (N)
31	Building 31 roof	P102	Y / (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y / (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y / (N)
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y / (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y / (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y / (N)
90	Building 31 look west to lower roof of LIB Plant	P129	Y / (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y / (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y / (N)
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y / (N)

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 7 5 16

CHECK COMPLETED BY: STEVE NIEWIADOMSKI

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y (N)
27	Building 31 roof look south of to roof of Building 27	P092	Y (N)
10A	Building 31 roof look north to roof of Building 10	P131	Y (N)
10C	Building 31 roof look north to roof of Building 10	P005	Y (N)
31	Building 31 roof	P010	Y (N)
31	Building 31 roof	P010	Y (N)
31	Building 31 roof	P010	Y (N)
31	Building 31 roof	P010-1	Y (N)
31	Building 31 roof	P024	Y (N)
31	Building 31 roof	P026	Y (N)
31	Building 31 roof	P026	Y (N)
31	Building 31 roof	P028/P110	Y (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y (N)
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y (N)
10	Building 31 roof look north to roof of Building 10	P069	Y (N)
16	Building 31 roof look north to roof of Building 16	P080	Y (N)
16	Building 31 roof look north to roof of Building 16	P080	Y (N)
16	Building 31 roof look north to roof of Building 16	P080	Y (N)
10	Building 31 roof look north to roof of Building 10	P094	Y (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y (N)
25	North side of Building 25	P098	Y (N)
25	North side of Building 25	P098	Y (N)
9	West side of Building 9	P099	Y (N)
9	Building 31 roof look west to east side wall of Building 9	P099	Y (N)
10C	Building 31 roof look north to roof of Building 10	P100	Y (N)
10C	Building 31 roof look north to roof of Building 10	P101	Y (N)
31	Building 31 roof	P102	Y (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y (N)
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y (N)
90	Building 31 look west to lower roof of LIB Plant	P129	Y (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y (N)
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y (N)

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 6/27/16

CHECK COMPLETED BY: T. F.

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y/N
27	Building 31 roof look south of to roof of Building 27	P092	Y/N
10A	Building 31 roof look north to roof of Building 10	P131	Y/N
10C	Building 31 roof look north to roof of Building 10	P005	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010-1	Y/N
31	Building 31 roof	P024	Y/N
31	Building 31 roof	P026	Y/N
31	Building 31 roof	P026	Y/N
31	Building 31 roof	P028/P110	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y/N
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y/N
10	Building 31 roof look north to roof of Building 10	P069	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
10	Building 31 roof look north to roof of Building 10	P094	Y/N
27	Building 31 roof look south of to roof of Building 27	P096	Y/N
27	Building 31 roof look south of to roof of Building 27	P096	Y/N
25	North side of Building 25	P098	Y/N
25	North side of Building 25	P098	Y/N
9	West side of Building 9	P099	Y/N
9	Building 31 roof look west to east side wall of Building 9	P099	Y/N
10C	Building 31 roof look north to roof of Building 10	P100	Y/N
10C	Building 31 roof look north to roof of Building 10	P101	Y/N
31	Building 31 roof	P102	Y/N
13	Building 31 roof look north west to roof of Building 13	P127	Y/N
13	Building 31 roof look north west to roof of Building 13	P127	Y/N
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y/N
90	Building 31 look west to east wall of LIB Plant	P129	Y/N
90	Building 31 look west to east wall of LIB Plant	P129	Y/N
90	Building 31 look west to lower roof of LIB Plant	P129	Y/N
90	Building 31 look west to upper roof of LIB Plant	P129	Y/N
90	Building 31 look west to upper roof of LIB Plant	P129	Y/N
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y/N

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 6/20/16

CHECK COMPLETED BY: [Signature]

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y (N)
27	Building 31 roof look south of to roof of Building 27	P092	Y (N)
10A	Building 31 roof look north to roof of Building 10	P131	Y (N)
10C	Building 31 roof look north to roof of Building 10	P005	Y (N)
31	Building 31 roof	P010	Y (N)
31	Building 31 roof	P010	Y (N)
31	Building 31 roof	P010	Y (N)
31	Building 31 roof	P010-1	Y (N)
31	Building 31 roof	P024	Y (N)
31	Building 31 roof	P026	Y (N)
31	Building 31 roof	P026	Y (N)
31	Building 31 roof	P028/P110	Y (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y (N)
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y (N)
10	Building 31 roof look north to roof of Building 10	P069	Y (N)
16	Building 31 roof look north to roof of Building 16	P080	Y (N)
16	Building 31 roof look north to roof of Building 16	P080	Y (N)
16	Building 31 roof look north to roof of Building 16	P080	Y (N)
10	Building 31 roof look north to roof of Building 10	P094	Y (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y (N)
25	North side of Building 25	P098	Y (N)
25	North side of Building 25	P098	Y (N)
9	West side of Building 9	P099	Y (N)
9	Building 31 roof look west to east side wall of Building 9	P099	Y (N)
10C	Building 31 roof look north to roof of Building 10	P100	Y (N)
10C	Building 31 roof look north to roof of Building 10	P101	Y (N)
31	Building 31 roof	P102	Y (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y (N)
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y (N)
90	Building 31 look west to lower roof of LIB Plant	P129	Y (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y (N)
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y (N)

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 6/14/16

CHECK COMPLETED BY: 

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y / (N)
27	Building 31 roof look south of to roof of Building 27	P092	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P131	Y / (N)
10C	Building 31 roof look north to roof of Building 10	P005	Y / (N)
31	Building 31 roof	P010	Y / (N)
31	Building 31 roof	P010	Y / (N)
31	Building 31 roof	P010	Y / (N)
31	Building 31 roof	P010-1	Y / (N)
31	Building 31 roof	P024	Y / (N)
31	Building 31 roof	P026	Y / (N)
31	Building 31 roof	P026	Y / (N)
31	Building 31 roof	P028/P110	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y / (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y / (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y / (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y / (N)
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y / (N)
10	Building 31 roof look north to roof of Building 10	P069	Y / (N)
16	Building 31 roof look north to roof of Building 16	P080	Y / (N)
16	Building 31 roof look north to roof of Building 16	P080	Y / (N)
16	Building 31 roof look north to roof of Building 16	P080	Y / (N)
10	Building 31 roof look north to roof of Building 10	P094	Y / (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y / (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y / (N)
25	North side of Building 25	P098	Y / (N)
25	North side of Building 25	P098	Y / (N)
9	West side of Building 9	P099	Y / (N)
9	Building 31 roof look west to east side wall of Building 9	P099	Y / (N)
10C	Building 31 roof look north to roof of Building 10	P100	Y / (N)
10C	Building 31 roof look north to roof of Building 10	P101	Y / (N)
31	Building 31 roof	P102	Y / (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y / (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y / (N)
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y / (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y / (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y / (N)
90	Building 31 look west to lower roof of LIB Plant	P129	Y / (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y / (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y / (N)
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y / (N)

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 6/6/16CHECK COMPLETED BY: T. J. [Signature]

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y / (N)
27	Building 31 roof look south of to roof of Building 27	P092	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P131	Y / (N)
10C	Building 31 roof look north to roof of Building 10	P005	Y / (N)
31	Building 31 roof	P010	Y / (N)
31	Building 31 roof	P010	Y / (N)
31	Building 31 roof	P010	Y / (N)
31	Building 31 roof	P010-1	Y / (N)
31	Building 31 roof	P024	Y / (N)
31	Building 31 roof	P026	Y / (N)
31	Building 31 roof	P026	Y / (N)
31	Building 31 roof	P028/P110	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y / (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y / (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y / (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y / (N)
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y / (N)
10	Building 31 roof look north to roof of Building 10	P069	Y / (N)
16	Building 31 roof look north to roof of Building 16	P080	Y / (N)
16	Building 31 roof look north to roof of Building 16	P080	Y / (N)
16	Building 31 roof look north to roof of Building 16	P080	Y / (N)
10	Building 31 roof look north to roof of Building 10	P094	Y / (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y / (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y / (N)
25	North side of Building 25	P098	Y / (N)
25	North side of Building 25	P098	Y / (N)
9	West side of Building 9	P099	Y / (N)
9	Building 31 roof look west to east side wall of Building 9	P099	Y / (N)
10C	Building 31 roof look north to roof of Building 10	P100	Y / (N)
10C	Building 31 roof look north to roof of Building 10	P101	Y / (N)
31	Building 31 roof	P102	Y / (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y / (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y / (N)
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y / (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y / (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y / (N)
90	Building 31 look west to lower roof of LIB Plant	P129	Y / (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y / (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y / (N)
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y / (N)

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 5/31/16CHECK COMPLETED BY: T. mg

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y/N
27	Building 31 roof look south of to roof of Building 27	P092	Y/N
10A	Building 31 roof look north to roof of Building 10	P131	Y/N
10C	Building 31 roof look north to roof of Building 10	P005	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010-1	Y/N
31	Building 31 roof	P024	Y/N
31	Building 31 roof	P026	Y/N
31	Building 31 roof	P026	Y/N
31	Building 31 roof	P028/P110	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y/N
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y/N
10	Building 31 roof look north to roof of Building 10	P069	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
10	Building 31 roof look north to roof of Building 10	P094	Y/N
27	Building 31 roof look south of to roof of Building 27	P096	Y/N
27	Building 31 roof look south of to roof of Building 27	P096	Y/N
25	North side of Building 25	P098	Y/N
25	North side of Building 25	P098	Y/N
9	West side of Building 9	P099	Y/N
9	Building 31 roof look west to east side wall of Building 9	P099	Y/N
10C	Building 31 roof look north to roof of Building 10	P100	Y/N
10C	Building 31 roof look north to roof of Building 10	P101	Y/N
31	Building 31 roof	P102	Y/N
13	Building 31 roof look north west to roof of Building 13	P127	Y/N
13	Building 31 roof look north west to roof of Building 13	P127	Y/N
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y/N
90	Building 31 look west to east wall of LIB Plant	P129	Y/N
90	Building 31 look west to east wall of LIB Plant	P129	Y/N
90	Building 31 look west to lower roof of LIB Plant	P129	Y/N
90	Building 31 look west to upper roof of LIB Plant	P129	Y/N
90	Building 31 look west to upper roof of LIB Plant	P129	Y/N
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y/N

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 5/23/2016CHECK COMPLETED BY: T. [Signature]

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coli	Y <input checked="" type="radio"/> N
27	Building 31 roof look south of to roof of Building 27	P092	Y <input checked="" type="radio"/> N
10A	Building 31 roof look north to roof of Building 10	P131	Y <input checked="" type="radio"/> N
10C	Building 31 roof look north to roof of Building 10	P005	Y <input checked="" type="radio"/> N
31	Building 31 roof	P010	Y <input checked="" type="radio"/> N
31	Building 31 roof	P010	Y <input checked="" type="radio"/> N
31	Building 31 roof	P010	Y <input checked="" type="radio"/> N
31	Building 31 roof	P010-1	Y <input checked="" type="radio"/> N
31	Building 31 roof	P024	Y <input checked="" type="radio"/> N
31	Building 31 roof	P026	Y <input checked="" type="radio"/> N
31	Building 31 roof	P026	Y <input checked="" type="radio"/> N
31	Building 31 roof	P028/P110	Y <input checked="" type="radio"/> N
10A	Building 31 roof look north to roof of Building 10	P031	Y <input checked="" type="radio"/> N
10A	Building 31 roof look north to roof of Building 10	P031	Y <input checked="" type="radio"/> N
10A	Building 31 roof look north to roof of Building 10	P031	Y <input checked="" type="radio"/> N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y <input checked="" type="radio"/> N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y <input checked="" type="radio"/> N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y <input checked="" type="radio"/> N
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y <input checked="" type="radio"/> N
10	Building 31 roof look north to roof of Building 10	P069	Y <input checked="" type="radio"/> N
16	Building 31 roof look north to roof of Building 16	P080	Y <input checked="" type="radio"/> N
16	Building 31 roof look north to roof of Building 16	P080	Y <input checked="" type="radio"/> N
16	Building 31 roof look north to roof of Building 16	P080	Y <input checked="" type="radio"/> N
10	Building 31 roof look north to roof of Building 10	P094	Y <input checked="" type="radio"/> N
27	Building 31 roof look south of to roof of Building 27	P096	Y <input checked="" type="radio"/> N
27	Building 31 roof look south of to roof of Building 27	P096	Y <input checked="" type="radio"/> N
25	North side of Building 25	P098	Y <input checked="" type="radio"/> N
25	North side of Building 25	P098	Y <input checked="" type="radio"/> N
9	West side of Building 9	P099	Y <input checked="" type="radio"/> N
9	Building 31 roof look west to east side wall of Building 9	P099	Y <input checked="" type="radio"/> N
10C	Building 31 roof look north to roof of Building 10	P100	Y <input checked="" type="radio"/> N
10C	Building 31 roof look north to roof of Building 10	P101	Y <input checked="" type="radio"/> N
31	Building 31 roof	P102	Y <input checked="" type="radio"/> N
13	Building 31 roof look north west to roof of Building 13	P127	Y <input checked="" type="radio"/> N
13	Building 31 roof look north west to roof of Building 13	P127	Y <input checked="" type="radio"/> N
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y <input checked="" type="radio"/> N
90	Building 31 look west to east wall of LIB Plant	P129	Y <input checked="" type="radio"/> N
90	Building 31 look west to east wall of LIB Plant	P129	Y <input checked="" type="radio"/> N
90	Building 31 look west to lower roof of LIB Plant	P129	Y <input checked="" type="radio"/> N
90	Building 31 look west to upper roof of LIB Plant	P129	Y <input checked="" type="radio"/> N
90	Building 31 look west to upper roof of LIB Plant	P129	Y <input checked="" type="radio"/> N
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y <input checked="" type="radio"/> N

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 5/16/16CHECK COMPLETED BY: 1 

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y (N)
27	Building 31 roof look south of to roof of Building 27	P092	Y (N)
10A	Building 31 roof look north to roof of Building 10	P131	Y (N)
10C	Building 31 roof look north to roof of Building 10	P005	Y (N)
31	Building 31 roof	P010	Y (N)
31	Building 31 roof	P010	Y (N)
31	Building 31 roof	P010	Y (N)
31	Building 31 roof	P010-1	Y (N)
31	Building 31 roof	P024	Y (N)
31	Building 31 roof	P026	Y (N)
31	Building 31 roof	P026	Y (N)
31	Building 31 roof	P028/P110	Y (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y (N)
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y (N)
10	Building 31 roof look north to roof of Building 10	P069	Y (N)
16	Building 31 roof look north to roof of Building 16	P080	Y (N)
16	Building 31 roof look north to roof of Building 16	P080	Y (N)
16	Building 31 roof look north to roof of Building 16	P080	Y (N)
10	Building 31 roof look north to roof of Building 10	P094	Y (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y (N)
25	North side of Building 25	P098	Y (N)
25	North side of Building 25	P098	Y (N)
9	West side of Building 9	P099	Y (N)
9	Building 31 roof look west to east side wall of Building 9	P099	Y (N)
10C	Building 31 roof look north to roof of Building 10	P100	Y (N)
10C	Building 31 roof look north to roof of Building 10	P101	Y (N)
31	Building 31 roof	P102	Y (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y (N)
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y (N)
90	Building 31 look west to lower roof of LIB Plant	P129	Y (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y (N)
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y (N)

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 5/9/16

CHECK COMPLETED BY: [Signature]

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y / (N)
27	Building 31 roof look south of to roof of Building 27	P092	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P131	Y / (N)
10C	Building 31 roof look north to roof of Building 10	P005	Y / (N)
31	Building 31 roof	P010	Y / (N)
31	Building 31 roof	P010	Y / (N)
31	Building 31 roof	P010	Y / (N)
31	Building 31 roof	P010-1	Y / (N)
31	Building 31 roof	P024	Y / (N)
31	Building 31 roof	P026	Y / (N)
31	Building 31 roof	P026	Y / (N)
31	Building 31 roof	P028/P110	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y / (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y / (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y / (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y / (N)
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y / (N)
10	Building 31 roof look north to roof of Building 10	P069	Y / (N)
16	Building 31 roof look north to roof of Building 16	P080	Y / (N)
16	Building 31 roof look north to roof of Building 16	P080	Y / (N)
16	Building 31 roof look north to roof of Building 16	P080	Y / (N)
10	Building 31 roof look north to roof of Building 10	P094	Y / (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y / (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y / (N)
25	North side of Building 25	P098	Y / (N)
25	North side of Building 25	P098	Y / (N)
9	West side of Building 9	P099	Y / (N)
9	Building 31 roof look west to east side wall of Building 9	P099	Y / (N)
10C	Building 31 roof look north to roof of Building 10	P100	Y / (N)
10C	Building 31 roof look north to roof of Building 10	P101	Y / (N)
31	Building 31 roof	P102	Y / (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y / (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y / (N)
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y / (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y / (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y / (N)
90	Building 31 look west to lower roof of LIB Plant	P129	Y / (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y / (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y / (N)
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y / (N)

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 5/2/16

CHECK COMPLETED BY: 

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y/N
27	Building 31 roof look south of to roof of Building 27	P092	Y/N
10A	Building 31 roof look north to roof of Building 10	P131	Y/N
10C	Building 31 roof look north to roof of Building 10	P005	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010-1	Y/N
31	Building 31 roof	P024	Y/N
31	Building 31 roof	P026	Y/N
31	Building 31 roof	P026	Y/N
31	Building 31 roof	P028/P110	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y/N
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y/N
10	Building 31 roof look north to roof of Building 10	P069	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
10	Building 31 roof look north to roof of Building 10	P094	Y/N
27	Building 31 roof look south of to roof of Building 27	P096	Y/N
27	Building 31 roof look south of to roof of Building 27	P096	Y/N
25	North side of Building 25	P098	Y/N
25	North side of Building 25	P098	Y/N
9	West side of Building 9	P099	Y/N
9	Building 31 roof look west to east side wall of Building 9	P099	Y/N
10C	Building 31 roof look north to roof of Building 10	P100	Y/N
10C	Building 31 roof look north to roof of Building 10	P101	Y/N
31	Building 31 roof	P102	Y/N
13	Building 31 roof look north west to roof of Building 13	P127	Y/N
13	Building 31 roof look north west to roof of Building 13	P127	Y/N
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y/N
90	Building 31 look west to east wall of LIB Plant	P129	Y/N
90	Building 31 look west to east wall of LIB Plant	P129	Y/N
90	Building 31 look west to lower roof of LIB Plant	P129	Y/N
90	Building 31 look west to upper roof of LIB Plant	P129	Y/N
90	Building 31 look west to upper roof of LIB Plant	P129	Y/N
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y/N

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 4/25/16

CHECK COMPLETED BY: 

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y/N
27	Building 31 roof look south of to roof of Building 27	P092	Y/N
10A	Building 31 roof look north to roof of Building 10	P131	Y/N
10C	Building 31 roof look north to roof of Building 10	P005	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010-1	Y/N
31	Building 31 roof	P024	Y/N
31	Building 31 roof	P026	Y/N
31	Building 31 roof	P026	Y/N
31	Building 31 roof	P028/P110	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y/N
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y/N
10	Building 31 roof look north to roof of Building 10	P069	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
10	Building 31 roof look north to roof of Building 10	P094	Y/N
27	Building 31 roof look south of to roof of Building 27	P096	Y/N
27	Building 31 roof look south of to roof of Building 27	P096	Y/N
25	North side of Building 25	P098	Y/N
25	North side of Building 25	P098	Y/N
9	West side of Building 9	P099	Y/N
9	Building 31 roof look west to east side wall of Building 9	P099	Y/N
10C	Building 31 roof look north to roof of Building 10	P100	Y/N
10C	Building 31 roof look north to roof of Building 10	P101	Y/N
31	Building 31 roof	P102	Y/N
13	Building 31 roof look north west to roof of Building 13	P127	Y/N
13	Building 31 roof look north west to roof of Building 13	P127	Y/N
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y/N
90	Building 31 look west to east wall of LIB Plant	P129	Y/N
90	Building 31 look west to east wall of LIB Plant	P129	Y/N
90	Building 31 look west to lower roof of LIB Plant	P129	Y/N
90	Building 31 look west to upper roof of LIB Plant	P129	Y/N
90	Building 31 look west to upper roof of LIB Plant	P129	Y/N
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y/N

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 04/18/16

CHECK COMPLETED BY: 

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y/N
27	Building 31 roof look south of to roof of Building 27	P092	Y/N
10A	Building 31 roof look north to roof of Building 10	P131	Y/N
10C	Building 31 roof look north to roof of Building 10	P005	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010-1	Y/N
31	Building 31 roof	P024	Y/N
31	Building 31 roof	P026	Y/N
31	Building 31 roof	P026	Y/N
31	Building 31 roof	P028/P110	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y/N
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y/N
10	Building 31 roof look north to roof of Building 10	P069	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
10	Building 31 roof look north to roof of Building 10	P094	Y/N
27	Building 31 roof look south of to roof of Building 27	P096	Y/N
27	Building 31 roof look south of to roof of Building 27	P096	Y/N
25	North side of Building 25	P098	Y/N
25	North side of Building 25	P098	Y/N
9	West side of Building 9	P099	Y/N
9	Building 31 roof look west to east side wall of Building 9	P099	Y/N
10C	Building 31 roof look north to roof of Building 10	P100	Y/N
10C	Building 31 roof look north to roof of Building 10	P101	Y/N
31	Building 31 roof	P102	Y/N
13	Building 31 roof look north west to roof of Building 13	P127	Y/N
13	Building 31 roof look north west to roof of Building 13	P127	Y/N
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y/N
90	Building 31 look west to east wall of LIB Plant	P129	Y/N
90	Building 31 look west to east wall of LIB Plant	P129	Y/N
90	Building 31 look west to lower roof of LIB Plant	P129	Y/N
90	Building 31 look west to upper roof of LIB Plant	P129	Y/N
90	Building 31 look west to upper roof of LIB Plant	P129	Y/N
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y/N

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 4/11/16

CHECK COMPLETED BY: T. M. F.

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y/N
27	Building 31 roof look south of to roof of Building 27	P092	Y/N
10A	Building 31 roof look north to roof of Building 10	P131	Y/N
10C	Building 31 roof look north to roof of Building 10	P005	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010-1	Y/N
31	Building 31 roof	P024	Y/N
31	Building 31 roof	P026	Y/N
31	Building 31 roof	P026	Y/N
31	Building 31 roof	P028/P110	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y/N
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y/N
10	Building 31 roof look north to roof of Building 10	P069	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
10	Building 31 roof look north to roof of Building 10	P094	Y/N
27	Building 31 roof look south of to roof of Building 27	P096	Y/N
27	Building 31 roof look south of to roof of Building 27	P096	Y/N
25	North side of Building 25	P098	Y/N
25	North side of Building 25	P098	Y/N
9	West side of Building 9	P099	Y/N
9	Building 31 roof look west to east side wall of Building 9	P099	Y/N
10C	Building 31 roof look north to roof of Building 10	P100	Y/N
10C	Building 31 roof look north to roof of Building 10	P101	Y/N
31	Building 31 roof	P102	Y/N
13	Building 31 roof look north west to roof of Building 13	P127	Y/N
13	Building 31 roof look north west to roof of Building 13	P127	Y/N
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y/N
90	Building 31 look west to east wall of LIB Plant	P129	Y/N
90	Building 31 look west to east wall of LIB Plant	P129	Y/N
90	Building 31 look west to lower roof of LIB Plant	P129	Y/N
90	Building 31 look west to upper roof of LIB Plant	P129	Y/N
90	Building 31 look west to upper roof of LIB Plant	P129	Y/N
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y/N

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 4/4/16CHECK COMPLETED BY: T. Angeli

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y/N
27	Building 31 roof look south of to roof of Building 27	P092	Y/N
10A	Building 31 roof look north to roof of Building 10	P131	Y/N
10C	Building 31 roof look north to roof of Building 10	P005	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010	Y/N
31	Building 31 roof	P010-1	Y/N
31	Building 31 roof	P024	Y/N
31	Building 31 roof	P026	Y/N
31	Building 31 roof	P026	Y/N
31	Building 31 roof	P028/P110	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
10A	Building 31 roof look north to roof of Building 10	P031	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y/N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y/N
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y/N
10	Building 31 roof look north to roof of Building 10	P069	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
16	Building 31 roof look north to roof of Building 16	P080	Y/N
10	Building 31 roof look north to roof of Building 10	P094	Y/N
27	Building 31 roof look south of to roof of Building 27	P096	Y/N
27	Building 31 roof look south of to roof of Building 27	P096	Y/N
25	North side of Building 25	P098	Y/N
25	North side of Building 25	P098	Y/N
9	West side of Building 9	P099	Y/N
9	Building 31 roof look west to east side wall of Building 9	P099	Y/N
10C	Building 31 roof look north to roof of Building 10	P100	Y/N
10C	Building 31 roof look north to roof of Building 10	P101	Y/N
31	Building 31 roof	P102	Y/N
13	Building 31 roof look north west to roof of Building 13	P127	Y/N
13	Building 31 roof look north west to roof of Building 13	P127	Y/N
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y/N
90	Building 31 look west to east wall of LIB Plant	P129	Y/N
90	Building 31 look west to east wall of LIB Plant	P129	Y/N
90	Building 31 look west to lower roof of LIB Plant	P129	Y/N
90	Building 31 look west to upper roof of LIB Plant	P129	Y/N
90	Building 31 look west to upper roof of LIB Plant	P129	Y/N
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y/N

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 3/28/16CHECK COMPLETED BY: TD

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y / N
27	Building 31 roof look south of to roof of Building 27	P092	Y / N
10A	Building 31 roof look north to roof of Building 10	P131	Y / N
10C	Building 31 roof look north to roof of Building 10	P005	Y / N
31	Building 31 roof	P010	Y / N
31	Building 31 roof	P010	Y / N
31	Building 31 roof	P010	Y / N
31	Building 31 roof	P010-1	Y / N
31	Building 31 roof	P024	Y / N
31	Building 31 roof	P026	Y / N
31	Building 31 roof	P026	Y / N
31	Building 31 roof	P028/P110	Y / N
10A	Building 31 roof look north to roof of Building 10	P031	Y / N
10A	Building 31 roof look north to roof of Building 10	P031	Y / N
10A	Building 31 roof look north to roof of Building 10	P031	Y / N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y / N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y / N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y / N
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y / N
10	Building 31 roof look north to roof of Building 10	P069	Y / N
16	Building 31 roof look north to roof of Building 16	P080	Y / N
16	Building 31 roof look north to roof of Building 16	P080	Y / N
16	Building 31 roof look north to roof of Building 16	P080	Y / N
10	Building 31 roof look north to roof of Building 10	P094	Y / N
27	Building 31 roof look south of to roof of Building 27	P096	Y / N
27	Building 31 roof look south of to roof of Building 27	P096	Y / N
25	North side of Building 25	P098	Y / N
25	North side of Building 25	P098	Y / N
9	West side of Building 9	P099	Y / N
9	Building 31 roof look west to east side wall of Building 9	P099	Y / N
10C	Building 31 roof look north to roof of Building 10	P100	Y / N
10C	Building 31 roof look north to roof of Building 10	P101	Y / N
31	Building 31 roof	P102	Y / N
13	Building 31 roof look north west to roof of Building 13	P127	Y / N
13	Building 31 roof look north west to roof of Building 13	P127	Y / N
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y / N
90	Building 31 look west to east wall of LIB Plant	P129	Y / N
90	Building 31 look west to east wall of LIB Plant	P129	Y / N
90	Building 31 look west to lower roof of LIB Plant	P129	Y / N
90	Building 31 look west to upper roof of LIB Plant	P129	Y / N
90	Building 31 look west to upper roof of LIB Plant	P129	Y / N
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y / N

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 3/21/16CHECK COMPLETED BY: TC

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y / (N)
27	Building 31 roof look south of to roof of Building 27	P092	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P131	Y / (N)
10C	Building 31 roof look north to roof of Building 10	P005	Y / (N)
31	Building 31 roof	P010	Y / (N)
31	Building 31 roof	P010	Y / (N)
31	Building 31 roof	P010	Y / (N)
31	Building 31 roof	P010-1	Y / (N)
31	Building 31 roof	P024	Y / (N)
31	Building 31 roof	P026	Y / (N)
31	Building 31 roof	P026	Y / (N)
31	Building 31 roof	P028/P110	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y / (N)
10A	Building 31 roof look north to roof of Building 10	P031	Y / (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y / (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y / (N)
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y / (N)
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y / (N)
10	Building 31 roof look north to roof of Building 10	P069	Y / (N)
16	Building 31 roof look north to roof of Building 16	P080	Y / (N)
16	Building 31 roof look north to roof of Building 16	P080	Y / (N)
16	Building 31 roof look north to roof of Building 16	P080	Y / (N)
10	Building 31 roof look north to roof of Building 10	P094	Y / (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y / (N)
27	Building 31 roof look south of to roof of Building 27	P096	Y / (N)
25	North side of Building 25	P098	Y / (N)
25	North side of Building 25	P098	Y / (N)
9	West side of Building 9	P099	Y / (N)
9	Building 31 roof look west to east side wall of Building 9	P099	Y / (N)
10C	Building 31 roof look north to roof of Building 10	P100	Y / (N)
10C	Building 31 roof look north to roof of Building 10	P101	Y / (N)
31	Building 31 roof	P102	Y / (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y / (N)
13	Building 31 roof look north west to roof of Building 13	P127	Y / (N)
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y / (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y / (N)
90	Building 31 look west to east wall of LIB Plant	P129	Y / (N)
90	Building 31 look west to lower roof of LIB Plant	P129	Y / (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y / (N)
90	Building 31 look west to upper roof of LIB Plant	P129	Y / (N)
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y / (N)

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 3/14/16

CHECK COMPLETED BY: TQ

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y / N
27	Building 31 roof look south of to roof of Building 27	P092	Y / N
10A	Building 31 roof look north to roof of Building 10	P131	Y / N
10C	Building 31 roof look north to roof of Building 10	P005	Y / N
31	Building 31 roof	P010	Y / N
31	Building 31 roof	P010	Y / N
31	Building 31 roof	P010	Y / N
31	Building 31 roof	P010-1	Y / N
31	Building 31 roof	P024	Y / N
31	Building 31 roof	P026	Y / N
31	Building 31 roof	P026	Y / N
31	Building 31 roof	P028/P110	Y / N
10A	Building 31 roof look north to roof of Building 10	P031	Y / N
10A	Building 31 roof look north to roof of Building 10	P031	Y / N
10A	Building 31 roof look north to roof of Building 10	P031	Y / N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y / N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y / N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y / N
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y / N
10	Building 31 roof look north to roof of Building 10	P069	Y / N
16	Building 31 roof look north to roof of Building 16	P080	Y / N
16	Building 31 roof look north to roof of Building 16	P080	Y / N
16	Building 31 roof look north to roof of Building 16	P080	Y / N
10	Building 31 roof look north to roof of Building 10	P094	Y / N
27	Building 31 roof look south of to roof of Building 27	P096	Y / N
27	Building 31 roof look south of to roof of Building 27	P096	Y / N
25	North side of Building 25	P098	Y / N
25	North side of Building 25	P098	Y / N
9	West side of Building 9	P099	Y / N
9	Building 31 roof look west to east side wall of Building 9	P099	Y / N
10C	Building 31 roof look north to roof of Building 10	P100	Y / N
10C	Building 31 roof look north to roof of Building 10	P101	Y / N
31	Building 31 roof	P102	Y / N
13	Building 31 roof look north west to roof of Building 13	P127	Y / N
13	Building 31 roof look north west to roof of Building 13	P127	Y / N
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y / N
90	Building 31 look west to east wall of LIB Plant	P129	Y / N
90	Building 31 look west to east wall of LIB Plant	P129	Y / N
90	Building 31 look west to lower roof of LIB Plant	P129	Y / N
90	Building 31 look west to upper roof of LIB Plant	P129	Y / N
90	Building 31 look west to upper roof of LIB Plant	P129	Y / N
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y / N

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 3/7/16CHECK COMPLETED BY: TD

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y / N
27	Building 31 roof look south of to roof of Building 27	P092	Y / N
10A	Building 31 roof look north to roof of Building 10	P131	Y / N
10C	Building 31 roof look north to roof of Building 10	P005	Y / N
31	Building 31 roof	P010	Y / N
31	Building 31 roof	P010	Y / N
31	Building 31 roof	P010	Y / N
31	Building 31 roof	P010-1	Y / N
31	Building 31 roof	P024	Y / N
31	Building 31 roof	P026	Y / N
31	Building 31 roof	P026	Y / N
31	Building 31 roof	P028/P110	Y / N
10A	Building 31 roof look north to roof of Building 10	P031	Y / N
10A	Building 31 roof look north to roof of Building 10	P031	Y / N
10A	Building 31 roof look north to roof of Building 10	P031	Y / N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y / N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y / N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y / N
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y / N
10	Building 31 roof look north to roof of Building 10	P069	Y / N
16	Building 31 roof look north to roof of Building 16	P080	Y / N
16	Building 31 roof look north to roof of Building 16	P080	Y / N
16	Building 31 roof look north to roof of Building 16	P080	Y / N
10	Building 31 roof look north to roof of Building 10	P094	Y / N
27	Building 31 roof look south of to roof of Building 27	P096	Y / N
27	Building 31 roof look south of to roof of Building 27	P096	Y / N
25	North side of Building 25	P098	Y / N
25	North side of Building 25	P098	Y / N
9	West side of Building 9	P099	Y / N
9	Building 31 roof look west to east side wall of Building 9	P099	Y / N
10C	Building 31 roof look north to roof of Building 10	P100	Y / N
10C	Building 31 roof look north to roof of Building 10	P101	Y / N
31	Building 31 roof	P102	Y / N
13	Building 31 roof look north west to roof of Building 13	P127	Y / N
13	Building 31 roof look north west to roof of Building 13	P127	Y / N
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y / N
90	Building 31 look west to east wall of LIB Plant	P129	Y / N
90	Building 31 look west to east wall of LIB Plant	P129	Y / N
90	Building 31 look west to lower roof of LIB Plant	P129	Y / N
90	Building 31 look west to upper roof of LIB Plant	P129	Y / N
90	Building 31 look west to upper roof of LIB Plant	P129	Y / N
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y / N

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 2/29/16

CHECK COMPLETED BY: TA

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y
27	Building 31 roof look south of to roof of Building 27	P092	Y
10A	Building 31 roof look north to roof of Building 10	P131	Y
10C	Building 31 roof look north to roof of Building 10	P005	Y
31	Building 31 roof	P010	Y
31	Building 31 roof	P010	Y
31	Building 31 roof	P010	Y
31	Building 31 roof	P010-1	Y
31	Building 31 roof	P024	Y
31	Building 31 roof	P026	Y
31	Building 31 roof	P026	Y
31	Building 31 roof	P028/P110	Y
10A	Building 31 roof look north to roof of Building 10	P031	Y
10A	Building 31 roof look north to roof of Building 10	P031	Y
10A	Building 31 roof look north to roof of Building 10	P031	Y
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y
10	Building 31 roof look north to roof of Building 10	P069	Y
16	Building 31 roof look north to roof of Building 16	P080	Y
16	Building 31 roof look north to roof of Building 16	P080	Y
16	Building 31 roof look north to roof of Building 16	P080	Y
10	Building 31 roof look north to roof of Building 10	P094	Y
27	Building 31 roof look south of to roof of Building 27	P096	Y
27	Building 31 roof look south of to roof of Building 27	P096	Y
25	North side of Building 25	P098	Y
25	North side of Building 25	P098	Y
9	West side of Building 9	P099	Y
9	Building 31 roof look west to east side wall of Building 9	P099	Y
10C	Building 31 roof look north to roof of Building 10	P100	Y
10C	Building 31 roof look north to roof of Building 10	P101	Y
31	Building 31 roof	P102	Y
13	Building 31 roof look north west to roof of Building 13	P127	Y
13	Building 31 roof look north west to roof of Building 13	P127	Y
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y
90	Building 31 look west to east wall of LIB Plant	P129	Y
90	Building 31 look west to east wall of LIB Plant	P129	Y
90	Building 31 look west to lower roof of LIB Plant	P129	Y
90	Building 31 look west to upper roof of LIB Plant	P129	Y
90	Building 31 look west to upper roof of LIB Plant	P129	Y
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 2/22/16CHECK COMPLETED BY: TR

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	N
27	Building 31 roof look south of to roof of Building 27	P092	N
10A	Building 31 roof look north to roof of Building 10	P131	N
10C	Building 31 roof look north to roof of Building 10	P005	N
31	Building 31 roof	P010	N
31	Building 31 roof	P010	N
31	Building 31 roof	P010	N
31	Building 31 roof	P010-1	N
31	Building 31 roof	P024	N
31	Building 31 roof	P026	N
31	Building 31 roof	P026	N
31	Building 31 roof	P028/P110	N
10A	Building 31 roof look north to roof of Building 10	P031	N
10A	Building 31 roof look north to roof of Building 10	P031	N
10A	Building 31 roof look north to roof of Building 10	P031	N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	N
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	N
10	Building 31 roof look north to roof of Building 10	P069	N
16	Building 31 roof look north to roof of Building 16	P080	N
16	Building 31 roof look north to roof of Building 16	P080	N
16	Building 31 roof look north to roof of Building 16	P080	N
10	Building 31 roof look north to roof of Building 10	P094	N
27	Building 31 roof look south of to roof of Building 27	P096	N
27	Building 31 roof look south of to roof of Building 27	P096	N
25	North side of Building 25	P098	N
25	North side of Building 25	P098	N
9	West side of Building 9	P099	N
9	Building 31 roof look west to east side wall of Building 9	P099	N
10C	Building 31 roof look north to roof of Building 10	P100	N
10C	Building 31 roof look north to roof of Building 10	P101	N
31	Building 31 roof	P102	N
13	Building 31 roof look north west to roof of Building 13	P127	N
13	Building 31 roof look north west to roof of Building 13	P127	N
13	Building 31 roof look north west to roof of Building 13	P127/P050	N
90	Building 31 look west to east wall of LIB Plant	P129	N
90	Building 31 look west to east wall of LIB Plant	P129	N
90	Building 31 look west to lower roof of LIB Plant	P129	N
90	Building 31 look west to upper roof of LIB Plant	P129	N
90	Building 31 look west to upper roof of LIB Plant	P129	N
27	Building 31 roof look south to roof of Building 27	P092 / P130	N

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 2/15/16CHECK COMPLETED BY: IA

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	N
27	Building 31 roof look south of to roof of Building 27	P092	N
10A	Building 31 roof look north to roof of Building 10	P131	N
10C	Building 31 roof look north to roof of Building 10	P005	N
31	Building 31 roof	P010	N
31	Building 31 roof	P010	N
31	Building 31 roof	P010	N
31	Building 31 roof	P010-1	N
31	Building 31 roof	P024	N
31	Building 31 roof	P026	N
31	Building 31 roof	P026	N
31	Building 31 roof	P028/P110	N
10A	Building 31 roof look north to roof of Building 10	P031	N
10A	Building 31 roof look north to roof of Building 10	P031	N
10A	Building 31 roof look north to roof of Building 10	P031	N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	N
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	N
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	N
10	Building 31 roof look north to roof of Building 10	P069	N
16	Building 31 roof look north to roof of Building 16	P080	N
16	Building 31 roof look north to roof of Building 16	P080	N
16	Building 31 roof look north to roof of Building 16	P080	N
10	Building 31 roof look north to roof of Building 10	P094	N
27	Building 31 roof look south of to roof of Building 27	P096	N
27	Building 31 roof look south of to roof of Building 27	P096	N
25	North side of Building 25	P098	N
25	North side of Building 25	P098	N
9	West side of Building 9	P099	N
9	Building 31 roof look west to east side wall of Building 9	P099	N
10C	Building 31 roof look north to roof of Building 10	P100	N
10C	Building 31 roof look north to roof of Building 10	P101	N
31	Building 31 roof	P102	N
13	Building 31 roof look north west to roof of Building 13	P127	N
13	Building 31 roof look north west to roof of Building 13	P127	N
13	Building 31 roof look north west to roof of Building 13	P127/P050	N
90	Building 31 look west to east wall of LIB Plant	P129	N
90	Building 31 look west to east wall of LIB Plant	P129	N
90	Building 31 look west to lower roof of LIB Plant	P129	N
90	Building 31 look west to upper roof of LIB Plant	P129	N
90	Building 31 look west to upper roof of LIB Plant	P129	N
27	Building 31 roof look south to roof of Building 27	P092 / P130	N

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 2/8/16CHECK COMPLETED BY: TA

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	
27	Building 31 roof look south of to roof of Building 27	P092	
10A	Building 31 roof look north to roof of Building 10	P131	
10C	Building 31 roof look north to roof of Building 10	P005	
31	Building 31 roof	P010	
31	Building 31 roof	P010	
31	Building 31 roof	P010	
31	Building 31 roof	P010-1	
31	Building 31 roof	P024	
31	Building 31 roof	P026	
31	Building 31 roof	P026	
31	Building 31 roof	P028/P110	
10A	Building 31 roof look north to roof of Building 10	P031	
10A	Building 31 roof look north to roof of Building 10	P031	
10A	Building 31 roof look north to roof of Building 10	P031	
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	
10	Building 31 roof look north to roof of Building 10	P069	
16	Building 31 roof look north to roof of Building 16	P080	
16	Building 31 roof look north to roof of Building 16	P080	
16	Building 31 roof look north to roof of Building 16	P080	
10	Building 31 roof look north to roof of Building 10	P094	
27	Building 31 roof look south of to roof of Building 27	P096	
27	Building 31 roof look south of to roof of Building 27	P096	
25	North side of Building 25	P098	
25	North side of Building 25	P098	
9	West side of Building 9	P099	
9	Building 31 roof look west to east side wall of Building 9	P099	
10C	Building 31 roof look north to roof of Building 10	P100	
10C	Building 31 roof look north to roof of Building 10	P101	
31	Building 31 roof	P102	
13	Building 31 roof look north west to roof of Building 13	P127	
13	Building 31 roof look north west to roof of Building 13	P127	
13	Building 31 roof look north west to roof of Building 13	P127/P050	
90	Building 31 look west to east wall of LIB Plant	P129	
90	Building 31 look west to east wall of LIB Plant	P129	
90	Building 31 look west to lower roof of LIB Plant	P129	
90	Building 31 look west to upper roof of LIB Plant	P129	
90	Building 31 look west to upper roof of LIB Plant	P129	
27	Building 31 roof look south to roof of Building 27	P092 / P130	

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 2/1/16CHECK COMPLETED BY: TA

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y
27	Building 31 roof look south of to roof of Building 27	P092	
10A	Building 31 roof look north to roof of Building 10	P131	
10C	Building 31 roof look north to roof of Building 10	P005	
31	Building 31 roof	P010	
31	Building 31 roof	P010	
31	Building 31 roof	P010	
31	Building 31 roof	P010-1	
31	Building 31 roof	P024	
31	Building 31 roof	P026	
31	Building 31 roof	P026	
31	Building 31 roof	P028/P110	
10A	Building 31 roof look north to roof of Building 10	P031	
10A	Building 31 roof look north to roof of Building 10	P031	
10A	Building 31 roof look north to roof of Building 10	P031	
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	
10	Building 31 roof look north to roof of Building 10	P069	
16	Building 31 roof look north to roof of Building 16	P080	
16	Building 31 roof look north to roof of Building 16	P080	
16	Building 31 roof look north to roof of Building 16	P080	
10	Building 31 roof look north to roof of Building 10	P094	
27	Building 31 roof look south of to roof of Building 27	P096	
27	Building 31 roof look south of to roof of Building 27	P096	
25	North side of Building 25	P098	
25	North side of Building 25	P098	
9	West side of Building 9	P099	
9	Building 31 roof look west to east side wall of Building 9	P099	
10C	Building 31 roof look north to roof of Building 10	P100	
10C	Building 31 roof look north to roof of Building 10	P101	
31	Building 31 roof	P102	
13	Building 31 roof look north west to roof of Building 13	P127	
13	Building 31 roof look north west to roof of Building 13	P127	
13	Building 31 roof look north west to roof of Building 13	P127/P050	
90	Building 31 look west to east wall of LIB Plant	P129	
90	Building 31 look west to east wall of LIB Plant	P129	
90	Building 31 look west to lower roof of LIB Plant	P129	
90	Building 31 look west to upper roof of LIB Plant	P129	
90	Building 31 look west to upper roof of LIB Plant	P129	
27	Building 31 roof look south to roof of Building 27	P092 / P130	

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 1/25/16CHECK COMPLETED BY: TA

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	
27	Building 31 roof look south of to roof of Building 27	P092	
10A	Building 31 roof look north to roof of Building 10	P131	
10C	Building 31 roof look north to roof of Building 10	P005	
31	Building 31 roof	P010	
31	Building 31 roof	P010	
31	Building 31 roof	P010	
31	Building 31 roof	P010-1	
31	Building 31 roof	P024	
31	Building 31 roof	P026	
31	Building 31 roof	P026	
31	Building 31 roof	P028/P110	
10A	Building 31 roof look north to roof of Building 10	P031	
10A	Building 31 roof look north to roof of Building 10	P031	
10A	Building 31 roof look north to roof of Building 10	P031	
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	
10	Building 31 roof look north to roof of Building 10	P069	
16	Building 31 roof look north to roof of Building 16	P080	
16	Building 31 roof look north to roof of Building 16	P080	
16	Building 31 roof look north to roof of Building 16	P080	
10	Building 31 roof look north to roof of Building 10	P094	
27	Building 31 roof look south of to roof of Building 27	P096	
27	Building 31 roof look south of to roof of Building 27	P096	
25	North side of Building 25	P098	
25	North side of Building 25	P098	
9	West side of Building 9	P099	
9	Building 31 roof look west to east side wall of Building 9	P099	
10C	Building 31 roof look north to roof of Building 10	P100	
10C	Building 31 roof look north to roof of Building 10	P101	
31	Building 31 roof	P102	
13	Building 31 roof look north west to roof of Building 13	P127	
13	Building 31 roof look north west to roof of Building 13	P127	
13	Building 31 roof look north west to roof of Building 13	P127/P050	
90	Building 31 look west to east wall of LIB Plant	P129	
90	Building 31 look west to east wall of LIB Plant	P129	
90	Building 31 look west to lower roof of LIB Plant	P129	
90	Building 31 look west to upper roof of LIB Plant	P129	
90	Building 31 look west to upper roof of LIB Plant	P129	
27	Building 31 roof look south to roof of Building 27	P092 / P130	

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 1/18/16CHECK COMPLETED BY: TA

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	
27	Building 31 roof look south of to roof of Building 27	P092	
10A	Building 31 roof look north to roof of Building 10	P131	
10C	Building 31 roof look north to roof of Building 10	P005	
31	Building 31 roof	P010	
31	Building 31 roof	P010	
31	Building 31 roof	P010	
31	Building 31 roof	P010-1	
31	Building 31 roof	P024	
31	Building 31 roof	P026	
31	Building 31 roof	P026	
31	Building 31 roof	P028/P110	
10A	Building 31 roof look north to roof of Building 10	P031	
10A	Building 31 roof look north to roof of Building 10	P031	
10A	Building 31 roof look north to roof of Building 10	P031	
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	
10	Building 31 roof look north to roof of Building 10	P069	
16	Building 31 roof look north to roof of Building 16	P080	
16	Building 31 roof look north to roof of Building 16	P080	
16	Building 31 roof look north to roof of Building 16	P080	
10	Building 31 roof look north to roof of Building 10	P094	
27	Building 31 roof look south of to roof of Building 27	P096	
27	Building 31 roof look south of to roof of Building 27	P096	
25	North side of Building 25	P098	
25	North side of Building 25	P098	
9	West side of Building 9	P099	
9	Building 31 roof look west to east side wall of Building 9	P099	
10C	Building 31 roof look north to roof of Building 10	P100	
10C	Building 31 roof look north to roof of Building 10	P101	
31	Building 31 roof	P102	
13	Building 31 roof look north west to roof of Building 13	P127	
13	Building 31 roof look north west to roof of Building 13	P127	
13	Building 31 roof look north west to roof of Building 13	P127/P050	
90	Building 31 look west to east wall of LIB Plant	P129	
90	Building 31 look west to east wall of LIB Plant	P129	
90	Building 31 look west to lower roof of LIB Plant	P129	
90	Building 31 look west to upper roof of LIB Plant	P129	
90	Building 31 look west to upper roof of LIB Plant	P129	
27	Building 31 roof look south to roof of Building 27	P092 / P130	

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 11/11/16

CHECK COMPLETED BY: TA

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	Y
27	Building 31 roof look south of to roof of Building 27	P092	Y
10A	Building 31 roof look north to roof of Building 10	P131	Y
10C	Building 31 roof look north to roof of Building 10	P005	Y
31	Building 31 roof	P010	Y
31	Building 31 roof	P010	Y
31	Building 31 roof	P010	Y
31	Building 31 roof	P010-1	Y
31	Building 31 roof	P024	Y
31	Building 31 roof	P026	Y
31	Building 31 roof	P026	Y
31	Building 31 roof	P028/P110	Y
10A	Building 31 roof look north to roof of Building 10	P031	Y
10A	Building 31 roof look north to roof of Building 10	P031	Y
10A	Building 31 roof look north to roof of Building 10	P031	Y
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	Y
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	Y
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	Y
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	Y
10	Building 31 roof look north to roof of Building 10	P069	Y
16	Building 31 roof look north to roof of Building 16	P080	Y
16	Building 31 roof look north to roof of Building 16	P080	Y
16	Building 31 roof look north to roof of Building 16	P080	Y
10	Building 31 roof look north to roof of Building 10	P094	Y
27	Building 31 roof look south of to roof of Building 27	P096	Y
27	Building 31 roof look south of to roof of Building 27	P096	Y
25	North side of Building 25	P098	Y
25	North side of Building 25	P098	Y
9	West side of Building 9	P099	Y
9	Building 31 roof look west to east side wall of Building 9	P099	Y
10C	Building 31 roof look north to roof of Building 10	P100	Y
10C	Building 31 roof look north to roof of Building 10	P101	Y
31	Building 31 roof	P102	Y
13	Building 31 roof look north west to roof of Building 13	P127	Y
13	Building 31 roof look north west to roof of Building 13	P127	Y
13	Building 31 roof look north west to roof of Building 13	P127/P050	Y
90	Building 31 look west to east wall of LIB Plant	P129	Y
90	Building 31 look west to east wall of LIB Plant	P129	Y
90	Building 31 look west to lower roof of LIB Plant	P129	Y
90	Building 31 look west to upper roof of LIB Plant	P129	Y
90	Building 31 look west to upper roof of LIB Plant	P129	Y
27	Building 31 roof look south to roof of Building 27	P092 / P130	Y

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken

WEEKLY VISUAL EMISSIONS CHECK

BASF ELYRIA

DATE: 1/4/16CHECK COMPLETED BY: TA

Building	Observation Point	Permit ID #	Visible Emissions Y/N
16	Building 31 roof look north to roof of Building 16	CTO/SCR Coll	
27	Building 31 roof look south of to roof of Building 27	P092	
10A	Building 31 roof look north to roof of Building 10	P131	
10C	Building 31 roof look north to roof of Building 10	P005	
31	Building 31 roof	P010	
31	Building 31 roof	P010	
31	Building 31 roof	P010	
31	Building 31 roof	P010-1	
31	Building 31 roof	P024	
31	Building 31 roof	P026	
31	Building 31 roof	P026	
31	Building 31 roof	P028/P110	
10A	Building 31 roof look north to roof of Building 10	P031	
10A	Building 31 roof look north to roof of Building 10	P031	
10A	Building 31 roof look north to roof of Building 10	P031	
25	Building 31 roof look northwest to roof Buildings 25 & 26	P050	
25	Building 31 roof look northwest to roof Buildings 25 & 26	P051	
25	Building 31 roof look northwest to roof Buildings 25 & 26	P055	
26	Building 31 roof look northwest to roof Buildings 25 & 26	P055-B	
10	Building 31 roof look north to roof of Building 10	P069	
16	Building 31 roof look north to roof of Building 16	P080	
16	Building 31 roof look north to roof of Building 16	P080	
16	Building 31 roof look north to roof of Building 16	P080	
10	Building 31 roof look north to roof of Building 10	P094	
27	Building 31 roof look south of to roof of Building 27	P096	
27	Building 31 roof look south of to roof of Building 27	P096	
25	North side of Building 25	P098	
25	North side of Building 25	P098	
9	West side of Building 9	P099	
9	Building 31 roof look west to east side wall of Building 9	P099	
10C	Building 31 roof look north to roof of Building 10	P100	
10C	Building 31 roof look north to roof of Building 10	P101	
31	Building 31 roof	P102	
13	Building 31 roof look north west to roof of Building 13	P127	
13	Building 31 roof look north west to roof of Building 13	P127	
13	Building 31 roof look north west to roof of Building 13	P127/P050	
90	Building 31 look west to east wall of LIB Plant	P129	
90	Building 31 look west to east wall of LIB Plant	P129	
90	Building 31 look west to lower roof of LIB Plant	P129	
90	Building 31 look west to upper roof of LIB Plant	P129	
90	Building 31 look west to upper roof of LIB Plant	P129	
27	Building 31 roof look south to roof of Building 27	P092 / P130	

VISIBLE EMISSIONS EVENT LOG

Color of Emissions	Is this VE event Representative of Normal Operations Y/N	If not from Normal Operations, what is the cause of abnormal operations	Duration of VE Event / minutes	Corrective Action taken